Linolair Lil & Cor	
Hobbs Herrico	○108 <b> 1,31,500</b>
Gentlemen:	Jato- 12-15-54
A review of the records for yo	our
in the Arrenteed Pool, which has a Gas Oil Ratio in excess	
of 100,000-1, indicates that this well should remain in the	
Oil pool. The Gas Oil Ratio limit in this Pool is, which	
means that gas production cannot exceed top allowable for the pool multiplied	
by the Gas Oil Ratio limit for the pool.	

ILLEGIBLE

Yours very truly,

OIL COMSERVATION COMMISSION

ALP/hs

Copy: OCC-Santa Fe. Transporter