| NO. OF COMES RECEIVED | | | |
|--|--------------------------------------|--|--|
| DISTRIBUTION | | | Form C-103 Supersedes Old |
| SANTAFE | NEW MEXICO OUL CO | INSERVATION COMMISSION | C-102 and C-103 |
| FILE | WEN MEXICO OFE CO | 435K + X LION COWWISSION | Effective 1-1-65 |
| U.S.G.S. | | | 5a. Indicate Type of Lease |
| LAND OFFICE | | | State X Fee |
| OPERATOR | | | 5. State Oil & Gas Lease No. |
| | | | 157 |
| SUNDRY | NOTICES AND PEPORTS C | DR VELLS | THE THE PROPERTY OF THE PARTY O |
| T. | FIRE PERMIT - PRODUCTION OF PER | G BACK 10 A DIFFERENT RESERVOIR. SUCH PROPUSALS.) | |
| OIL [V] GAS [7] | | | 7. Unit Agreement Name |
| Z. None of Operator | OTHER. | | |
| | | | 8. Farm of Lease Name |
| Atlantic Richfield Company 3. Address of Contrator | | | State 157 "D" |
| | Now Move on 20040 | | 9. Well No. |
| P. O. Box 1710, Hobbs, New Mexico 88240 | | | 1 8 |
| М 331 | 0 | | 10. Field and Pool, or Wildeat |
| UNIT LETTER M . 330 | FEET FROM THE SOUTH | LINE AND 990 FEET FRO | Arrowhead Grayburg |
| THE West | 12 2 | | |
| THE West LINE, SECTION | TOWNSHIP Z. | RANGE NMP | |
| | 15. Elevation (Show whether | er DF, RT, GR, etc.) | |
| | 3498 | · | 12, County |
| Check Ant | | | Lea |
| NOTICE OF INTE | FINION TO | Nature of Notice, Report or O | ther Data |
| • | | SUBSEQUEN | NT REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON X | REMEDIAL WORK | |
| TEMPORARILY ABANDON | . (22 | COMMENCE DRILLING DPNS. | ALTERING CASING |
| PULL OR ALTER CASING | CHANGE PLANS | CASING TEST AND CEMENT JOB | PLUG AND ABANDONMENT |
| | | OTHER | |
| OTHER | | | |
| 17. Describe Proposed or Completed Cherat | tons (Clearly state all mostice A. | 1 | |
| Describe Proposed or Completed Operat work) SEE RULE 1103. | Tons (Stearly state art pertinent de | taits, and give pertinent dates, including | g estimated date of starting any proposed |
| The above well was shut-in | on $5/1/68$ because if | t was uneconomical to pro | oduce. There are no other |
| est. | - imis well is preser | ntly completed OH 3665-37 | 777'. TD 3777'. Top of |
| bart w 1442 . base of sai | .t Z552'. | | 10001 |
| 8-5/8" OD 32# csg set @ 27 | 8' & cmtd w/150 sx. | | |
| 5-1/2" OD 17# csg w/6' of | 7 OD 24# csg on top | set @ 3665' & cmtd w/150 | osx. |
| Propose to plug & abandon 1. Rig up, kill well, inst | in the following mann | ier: | |
| 2. RIH w/5 $\frac{1}{2}$ " cmt retr on 2 | all BOP & POH W/Compi | etion assy. | |
| 3. Displace 65 sx Cl C cmt | cont's 4% sol thrus | retr@ 3565'. | |
| 1. Fill hole w/heavy gelle | d mud between all cmt | err @ 3565', pull out of | retr & spot 5 sx on top. |
| O. Run free point on 5름''O | D csg. cut & null fro | om free point estimated | to be @ 05501 |
| o por op sy cr c cut con | ∪g 4% gel across 5⊹ | OD csg stub & battom of | co be wapprox 2550. |
| · spot of sx cr c cmt con | t'g 4% gel across ton | of salt @ 1442' | - Sait @ 2000 . |
| o. Spot 40 sx Cl C cmt con | t'g 4% gel across 8-5 | 1/8" cer chan @ 270! | |
| 9. Spot 10 sx cmt @ surface | e, install regulation | dry hole marker, clean | & level location. |
| وور من المراجعة | NISSION MUST BE NOTIFIED | 24 | |
| 10 00 DA | THE RECEIPEDING | OF C | |
| HULKS TA BILCOMO | OPERATIONS FOR THE CA | 03 GY. | peres 10/1/76 |
| TO BE APP | ROYED. | _ | |
| . I hereby certify that the information above | e is true and complete to the best | of my knowledge and helief | |


Dist. Drlg. Supv.

5/26/76

Mount 1 is

ONDITIONS OF APPROVAL, IF ANY:

Jerry Jonesa Dist 1, Saper



ATLANTIC RICHFIELD COMPANY Blow Out Preventer Program

| Lease Name_ | State 157 "D" |
|-------------|----------------------------|
| Well No | 8 |
| Location_ | 330' FSL & 990' FWL |
| | Sec 12-22S-36E, Lea County |

BOP to be tested before installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.