

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.  
30-025-08900

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Arrowhead Grayburg Unit

8. Well No.  
223

9. Pool name or Wildcat  
Arrowhead-Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter D : 330 feet from the north line and 990 feet from the west line

Section 13 Township 22-S Range 36-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Tag 5 1/2 CIBP @ 3645' spot 35sx plug fr/3645-3406(Grayburg-Queens) Tag @ 3410' (OK w/EL. w/OCD)
2. Displace hole w/MLF, 9.5# Brine w/25# gel p/BBL
3. Spot 25sx plug fr/2640' to 2540' (B-salt) Tag @ 2418'
4. Spot 25sx plug fr/1500' to 1400' (T-salt) Tag @ 1281'
5. Perf 4 holes @ 388' circ cmt between 5 1/2" X 9 5/8" csg w/130sx (9 5/8" shoe) Tag @ 10 fr/surf
6. Install dry hole marker 9-26-02

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER DATE 9-26-02

Type or print name JIMMY BAGLEY Telephone No. 915 520-8756  
(This space for State use)

APPROVED BY [Signature] TITLE GARY W WINK FEB 13 2003  
Conditions of approval, if any:

GARY W WINK  
OIL FIELD REPRESENTATIVE II/STAFF MANAGER

GWW

[Signature] Rd Rep 3-6-03