

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08915 08914
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A-2614
7. Lease Name or Unit Agreement Name McDonald WN State
8. Well No. 15
9. Pool name or Wildcat Jalomat Tensill South Eunice Yates SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator PO Box 2409, Hobbs, NM 88240	
4. Well Location Unit Letter L : 6501650 Feet From The South Line and 330' Feet From The West Line Section 15 Township 22-S Range 36-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 8/4/93 1. Drill out cement plug from 3496' to 3511'.
8/6/93 2. Perforate 4 squeeze holes @ 3510'.
3. Set cement retainer @ 3507'.
4. Pump 25 sx Class C cement w/.3% Halad 9 in attempt to isolate Lower Seven Rivers and Jalomat formations.
8/7/93 5. RIH w/bit & tbg @ 3499'. POOH w/bit.
8/11/93 6. RIH & set 6 5/8" Baker AD-1 tension packer @ 3350'.
7. Acidize csg rip 3400-3499' w/2000 gal 15% NEFE HCl acid. CKG
8. Swab well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tony Hallum TITLE Production Foreman DATE 8/23/93
TYPE OR PRINT NAME Tony Hallum TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 07 1993

RECEIVED

SEP 02 1993

**NEW YORK
OFFICE**