NEW MEX) OIL CONSERVATION COMMISS Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission. of the Commission.

•	nqicate natur	e or repor	by checking below	₩:	
REPORT ON BEGINNING DRILLING OPERATIONS REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL REPORT ON RESULT OF TEST OF CASING SHUT-OFF			REPORT ON RE	EPAIRING WELL	
		42	REPORT ON PULLING OR OTHERWISE ALTERING CASING		
		X	REPORT ON DE	EPENING WELL	
REPORT ON RESULT OF PLUGGING (F WELL				
	Hobbs, New	Mexico	, August 21,	1937	
			Place	Da	te
OIL CONSERVATION COMMISSION Santa Fe, New Mexico.	Ν,				
Gentlemen:					
Following is a report on the work of	one and the i	results obta	ined under the he	ading noted above at t	he
The Ohio Oil Company	State 1	McDonald		Wall No	8
Swa Swa	16	_	Lease	Well No	in the
· · · · · · · · · · · · · · · · · · ·	of Sec.	 , '	r. 22 8	, R	, N. M. P. M.,
Eunice	Field,	A		Monument	County.
he dates of this work were as follo	ws:	Augu	st 19, 1937		
Notice of intention to do the work w	as [was not]	submitted	on Form C-102 on	Aug 14, 19	37 19
nd approval of the proposed plan w	as [Way Hot]	obtained.	(Cross out incorre	ect words.)	
Ran 3667 feet of 7" O.D. C			2	632	
	D(!	, ,			
G. R. McGle ther		The Ohio	Di Company	17 TEO	rom a n
Vitnessed by	me		Company		Title
Subscribed and sworm to before August	e this 21 t , 19 tary Public h 2, 1941	18 N	osition The	Supt Company or Operat	
My Commission expires.		A	idress He b	s, New Mexico	
Remarks:				Just	repard
				√ 1 & Ga	s Anspector

Title