

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 030132 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Closson C

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18-223-36E

12. COUNTY OR PARISH 13. STATE

Lee

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

Dec 20 10 52 AM '66

1. OIL WELL ☐ GAS WELL ☐ ☒ OTHER

2. NAME OF OPERATOR

Citrus Service Oil Company

3. ADDRESS OF OPERATOR

Box 69 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL 660' FEL Sec. 18-T223-R36E

Lee County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3588 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Old TD 3814 Line - PSTD 3395 well complete. Pulled tubing. Perf. 182 holes (3117-3168) and 22 holes (3177-3188) Set a retrievable SP at 3191. Ran tubing with a packer at 3077 acidized perfs. (3117-3188) w/500 gals. acid @ rate of 3 B/N @ 1500 psi, 5 min. S.I. Press. vacuum. Flowed @ rate of 135.2 MCFFD @ 40 psi TP. Re-acidized perfs. (3117-3188) w/10,000 gals. @ rate of 5.8 B/N min. press. 1500 PSI. Pulled packer and retrievable SP @ 3191. Ran tubing w/Hookwell packer set @ 3098. Recovered load and flowed 4 80 + 11 BW + 612.4 MCF - Gas/24 hours thru 3/4" choke, FTP 40 PSI thru perfs. 3117-3168, 3177-3188, 3200-3212, 3216-3230, 3236-3252, 3276-3290, 3292-3305, 3308-3318, and 3332-3350. Production before workover was 145 MCFFD. Well was recompleted July 26, 1965.

18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED

SIGNED C. D. GORDON

TITLE District Clerk

DATE 12-12-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DEC 14 1966

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 5: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

DEC 50 10 25 AM '68
U.S. GOVERNMENT PRINTING OFFICE