

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

FOR APPROVAL  
Budget Bureau No. 42-11424  
5. LEASE DESIGNATION AND SERIAL NO.

91-003418 LC 030132 (a)  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
(Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR  
Cities Service Company

3. ADDRESS OF OPERATOR  
P.O. Box 1919, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1980' FSL 660' FEL of Sec. 18, T22S, R36E  
Lea County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3598' DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Closson "C"

9. WELL NO.  
3

10. FIELD AND POOL, OR WILDCAT  
Jalmat Yates

11. SEC., T., R., M., OR B.R. AND SURVEY OR AREA  
Sec. 18, T22S, R36E

12. COUNTY OR PARISH  
Lea

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PUT IN OR ALTER CASING ☐  
MULTIPLE COMPLETION ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Accomplishment Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged in the following manner:

1. MIRU casing pulling unit, loaded hole W/mud laden fluid.
2. Spotted 15 sx cement on top of CIBP at 3200'. PB to 3150' W/cement. POOH W/TBG.
3. Shot 7" casing at 2409'. Spotted cmt plug 2550-2341- across 7" stub at 2409'. Tagged cmt. Plug W/WL at 2323'. 9-5/8" casing not recoverable.
4. Shot 2 1/2" holes in 9-5/8" csg. at 1600'. Pumped 170 sx cmt into perfs. At 1600' through retainer set at 1417'. Left 10 sx in csg. below retainer and displaced 160 sx out perfs. in 9-5/8".
5. Spotted 25 sx plug in 9-5/8" from surface to 50' and installed 4" dry hole marker. Albert Means W/USGS witnessed.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Region Operations Manager

DATE

April 12, 1978

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

