

Form 9-331 a (Feb. 1951)





Budget Bureau 42-R358.2. Approval expires 12-31-52.

Land Office Land Office Lease No. 030132-.5 Unit Closson -3

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING							
					NOTICE OF INTENTION TO RE-DRILL OR	REPAIR WELL		ORT OF REDRILLING OR RE	
					NOTICE OF INTENTION TO SHOOT OR A	į.	li .	ORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALT	ER CASING	<i>r</i>							
NOTICE OF INTENTION TO ABANDON WE									
(INDICATE	ABOVE BY CHECK MARK	NATURE OF REPORT, NOT	TCE, OR OTHER DATA)						
		ΰu	ne 20	, 19 <sup>50</sup>					
Well No5 is locat		<b>V</b> / //	` ,	ine of sec. 18					
1/4 Sec. 18 (% Sec. and Sec. No.)	22S (Twp.)	362 (Range)	(Meridian)						
South-Sunice		Lea	New Yex	ico					
(Field)		or Subdivision)	(State or T						
It is recommend that Welbe plugged and chandoned Well to. 5 on the Closs lift methods failed to plad successfully been recommend the upper part of this well might possible pool well.  All attempts to find oil of the work over is as in	il No. 5 on the lafter all rates on-3 Lease die produce anythic ecompleted as of the seven hery se recomplete or gas in the	ne Closson-B F sclaimable cas ed due to wate ing but water. gas wells by livers produci eted as a gas e uper Seven R	ederal Lease (hing is pulled. rencroachment Since other we plugging off thing horixon it well even thoug ivers failed an	o.030132-3) and artifical alls in the field the water and perform as believed that the it was an edge					
I understand that this plan of work m  Company Cities Serve  Address Priwer G., No.	ice Oil Compar	ny co	al Survey before operations						
	,	•							
		T:.1	District Supe	rintendent					