

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection Well</u>	7. Unit Agreement Name <u>South Eunice</u>
2. Name of Operator <u>Continental Oil Company</u>	8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator <u>Box 460 Hobbs, N. M. 88240</u>	9. Well No. <u>18</u>
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>22-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Eunice 7-Rivers Pumped South</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3532' GR.</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Water Shut Off</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted sand & Cal-seal to 3723'. Set pkr @ 3601'.  
Pumped 500 gals BT SAF III & followed w/35 sks. Class "C"  
Cement w/3# salt/sack. Press. test to 500# ok. Ran 5 1/8" bit  
& tag cmt @ 3661'. Drld cmt to 3700'. Unable to regain circ. Set  
pkr. @ 3601 & test sq. w/1000 psi. Press. declined to 550 psi. Released  
rig to Gulf to squeeze off Tolmat gas ports. Tolmat gas  
zone squeezed off & abandoned. Inj. 300 BWPD on vacuum.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE SI. Analyst DATE 6-20-76

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: