+Submit 3 Copies t Appropriate

State of New Mexico

Form C 103 Energy, Muserals and Natural Resources Department Revised 1-1-89 District Office DISTRICT I P.O. Box 1980, Hobbs, NM S8240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30-025-08975 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE •APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Well X OTHER South Eunice Unit 2. Name of Operator 8. Well No. Conoco Inc. 3. Address of Operator 9. Pool name or Wildcat 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500 Eunice 7 Rivers Queen, So. 4. Well Location Unit Letter L 1980 South 660 Feet From The __ Line and _ West Feet From The Line Section Township **22S** Range NMPM 36E County 10. Elevation (Show whether DF, RKB. RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON **REMEDIAL WORK** ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to perform a Casing Integrity Test on this well in preparation for requesting temporary abandonment approval, per the attached recommendation and procedure. When completed, a successful pressure test will be submitted to request temporary abandon status. formation above is true and complete to the best of my knowledge and belief. Sr. Staff Regulatory Assistant 07/13/99 TYPE OR PRINT NAME Reesa R. Wilkes TELEPHONE NO. 915/686-5580

Distribution: OCD (3), SHEAR, Ponca, Cost Asst., Well File, Field

CHIGINAL E PLETITY DIS - M

(this space for State Use)

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-

South Eunice Unit #17 30-025-08975

Recommendation to Temp. Abandon

This well is currently inactive. It is recommended that the well be temporarily abandoned in order to preserve future value.

- 1. RIH w/ 2 7/8" work string & cement squeeze casing (@ 630') w/75 sxs Class C cmt.
- 2. POOH and load casing with water and repair surface casing (@ 4') with welded patch job.
- 3. Drill out cmt in 5.5" 14# production casing and spot 35' cement on top of RBP (already set @ 3565').
- 4. Circulate Casing with inhibited packer fluid.
- 5. Pressure test casing to 500# for 30 minutes. Give OCD 24 hrs notice prior to pressure test.