

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☐	Fee ☒
5. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name <u>South Eureka Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>South Eureka Unit</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>3</u>
4. Location of Well UNIT LETTER <u>B</u> <u>330</u> FEET FROM THE <u>north</u> LINE AND <u>1650</u> FEET FROM THE <u>east</u> LINE, SECTION <u>21</u> TOWNSHIP <u>22 S</u> RANGE <u>36 E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Eureka Unit South</u>
15. Elevation (Show whether DF, RT, GR. etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER <u>Open Add'l Pay & Acidize</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work Started 7/8/87. MIRU Tag fell at 3791'. Co in hole w/csg scraper to 3788'. POOH. Clean out to 3806'. Set RBP at 3759'. Pull pkr up to 3741'. Pressure to 500 psi. Rel pkr & G1H to 3754'. Load hole & circulate wellbore clean w/150 bbls 2% KCL TFW w/1:1000 gals Adomall. MIRU. Spot 6 1/2 bbls 15% HCL-NE-FE acid from 3754'-3781'. Flush w/20 bbls 2% KCL TFW w/1:1000 gals Adomall. POOH w/2 7/8" Hg, pkr & on-off tool. G1H w/collar locator & tag RBP at 3759'. POOH running collar log. G1H w/4" csg gun & collar locator. Perf w/2 spf at 3572'-3600' & w/4 spf at 3672'-3754' for total of 91' & 303 shots. G1H w/on-off tool, treating pkr, SN & 2 7/8" Hg to top of RBP at 3759'. Pull pkr & set at 3555'. Swab well. Recover RBP at 3806' & POOH.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DF FINNEY

TITLE Administrative Supervisor

DATE January 4, 1988

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN - 5 1988