Form 9-331 (May 1963)	DEPA	UNITED STATES RTMENT OF THE IN GEO. SICAL SURV	ITERIOR 👯	BMIT IN TRIPLICAT ther instructions on se side:	Form approach Budget But 5. LEASE DESIGNATIO	N AND SERIAL NO.
	this form for p	OTICES AND REPO	r nlug bakek so a		6. IF INDIAN, ALLOTT	EE OR TRIBE NAME
OIL X W	S OTHE				7. UNIT AGREEMENT	NAME
2. NAME OF OPERA		······································	M		8. FARM OR LEASE NA	AME
Contine nt	al Oil Com	pany	U. s.	•	mar 6	-22
3. ADDRESS OF OPE	RATOR		F_{i}		8. WELL NO.	-2.6
P. O. Box	460, Hobb	s, New Mexico 882	40	r ton	2	
4. LOCATION OF WE See also space 1 At surface	LL - Report locati	O. FIELD AND POOL,	O. FIELD AND POOL, OB WILDCAT			
990' FS.	c + 16.	50' FWL 17 5	Sec.22		11. SEC., T., R., M., GR SURVEY OR ARE	
					Sec. 22 T-2	25 F- 366
14. PERMIT NO.		15. ELEVATIONS (Show wh		E.,)	12. COUNTY OR PARIS	H 13. STATE
		35/2'	DF		Ba	NM
nent to this we	ED OR COMPLETED	ABANDON* CHANGE PLANS OPERATIONS (Clearly state all rectionally drilled, give subsurfa	SE (O	Completion or Recon	attering ABANDONM ts of multiple completion spiction Report and Log f. is. including estimated da ical depths for all marke	on Well
		at temp. aban. com	menced.	1-67		•
Reason for	temp. aba	an.: UACCONOM	nenced. ID		•	
Future pla	ans for We	11:				
	Holdi	ing for second	dary re	covery		
					·	

ter for the territories and the solution them and followed when

*See Instructions on Reverse Side

NAV 5 1974

Em Sine

ACTING ENTINET FNGINEED