

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-030/33(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Continental oil Co.	8. FARM OR LEASE NAME Meyer B-22
3. ADDRESS OF OPERATOR Box 460 Hobbs, N. Mex	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL and 1980' FWL of Sec 22	10. FIELD AND POOL, OR WILDCAT
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3518' gr
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22, T-22S, R-36E
	12. COUNTY OR PARISH Lee
	13. STATE N. Mex

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perf w/2 j spf @ 3210', 3255', 3260', 3292', 3310', 3315', 3328', 3338', 3341', 3350', 3354', 3370' and 3372'. Set RBP @ $\pm$ 3420' and packer at $\pm$ 3385'. Treat 3390'-3428' w/1000 gals 15% HCL-NE acid. Set RBP @ $\pm$ 3385' and packer @ $\pm$ 3332' and treat perfs 3338'-3375' w/1200 gals 15% HCL-NE acid. Set RBP @ $\pm$ 3332' and packer at $\pm$ 3200' and treat perfs 3240'-3328' w/1400 gals 15% HCL-NE acid.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Gault

TITLE

Admin Supervisor

DATE

10-2-72

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

OCT 5 1972

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

USGS(S) NMFC(4) File