

DEBELLING REPORT

June 9, 1979	Rig up X-vert Well Service unit. Pull rods, install B.O.P. and pull tubing. (126 3/4" rods and 10' joints tubing 3154' plus seating nipple, perforator nipple and 19' mud anchor.
June 10, 1979	Did not work.
June 11, 1979	Did not work.
June 12, 1979	Rig up X-vert reverse rig. Pick up 4 3/4" bit and 8- 3 1/8" drill collars. Cleaned out 7 7/8" hole from bottom of casing at 3200' to 3490'. Make approximately two feet of hole. Pull up in casing and shut down for night.
June 13, 1979	Reverse cut four feet fill. Drill to 3503'. Pull tubing to change bit. Run button bit. At 7:00 A.M. drilling at 3576'.
June 14, 1979	Drilling at 3576'.
June 15, 1979	Drilling at 3712'.
June 16, 1979	Drilling at 3774'.
June 17, 1979	Drilling at 3829'.
June 18, 1979	O.D. 3914'.

Run	11.50'	Flotshoe 4" O.D. 11.5# x rd.
	11.50'	Shoe joint 4" O.D. 11.35# x rd.
	1.3"	Running collar 4" rd.
by job.	100.00'	4" O.D. L.L. Synairil P.C.
	10.00'	4" O.D. run in Gyflo Hammer-Packer
Total	334.18'	

C.H. JUNI #1 SUN RECORD
LEA COUNTY, NEW MEXICO

DRILLING REPORT

June 9, 1979	Rig up X-Pert Well Service unit. Pull rods, install B.O.P. and pull tubing. (126 3/4" rods and 102 joints tubing 3154' plus seating nipple, perforated nipple and 15' mud anchor.																						
June 10, 1979	Did not work.																						
June 11, 1979	Did not work.																						
June 12, 1979	Rig up X-Pert reverse rig. Pick up 4 3/4" bit and 8- 3 1/8" drill collars. Cleaned out 7 7/8" hole from bottom of casing at 3200' to 3490'. Make approximately two feet of hole. Pull-up in casing and shut down for night.																						
June 13, 1979	Reverse out four feet fill. Drill to 3508'. Pull tubing to change bit. Ran button bit. At 7:00 A.M. drilling at 3576'.																						
June 14, 1979	Drilling at 3576'.																						
June 15, 1979	Drilling at 3712'.																						
June 16, 1979	Drilling at 3774'.																						
June 17, 1979	Drilling at 3829'.																						
June 18, 1979	<table border="0"> <tbody> <tr> <td>T.D. 3914'.</td> <td></td> <td></td> </tr> <tr> <td>Ran</td> <td>1.25'</td> <td>floatshoe 4" O.D. 11.34# 8 rd.</td> </tr> <tr> <td></td> <td>16.00'</td> <td>shoe joint 4" O.D. 11.34# 8 rd.</td> </tr> <tr> <td></td> <td>.63"</td> <td>landing collar 8 rd.</td> </tr> <tr> <td>33 jts.</td> <td>903.00'</td> <td>4" O.D. 11.34# Hydril F. J.</td> </tr> <tr> <td></td> <td>10.00'</td> <td>4" O.D. Baker Hyflo Hanger-Packer</td> </tr> <tr> <td>Total</td> <td>931.18'</td> <td></td> </tr> </tbody> </table>		T.D. 3914'.			Ran	1.25'	floatshoe 4" O.D. 11.34# 8 rd.		16.00'	shoe joint 4" O.D. 11.34# 8 rd.		.63"	landing collar 8 rd.	33 jts.	903.00'	4" O.D. 11.34# Hydril F. J.		10.00'	4" O.D. Baker Hyflo Hanger-Packer	Total	931.18'	
T.D. 3914'.																							
Ran	1.25'	floatshoe 4" O.D. 11.34# 8 rd.																					
	16.00'	shoe joint 4" O.D. 11.34# 8 rd.																					
	.63"	landing collar 8 rd.																					
33 jts.	903.00'	4" O.D. 11.34# Hydril F. J.																					
	10.00'	4" O.D. Baker Hyflo Hanger-Packer																					
Total	931.18'																						