

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 09008
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  H.S. RECORD
8. Well No. 2
9. Pool name or Wildcat JALMAT (TAN YATES 7 RIV.)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3520' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator MERIDIAN OIL INC.	3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line Section 22 Township 22S Range 36E NMPM Lea County
---	--	--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Install BOPE. POH w/ tubing. RIH w/ 2 3/8" tubing, scraper and bit to 3175. Circulate hole w/ 10 ppg gelled brine mud. POH w/ tubing.

RIH w/ 5-1/2" CICR on 2-3/8" tbg and set @ 3150'. Pump 50 sx Class C cement through retainer. Pull out of CICR and dump 25 sx on top.

Pick up to 1650'. Spot 25 sx Class C cement plug.

POH w/ tbg. ND BOPE. RIH w/ tbg to +/- 241'. Spot 25 sx Class C cement plug and circulate to surface. Cut casing 3' below surface. Weld plate and abandonment marker to casing. Restore location as directed.

THE COMMISSION MUST BE NOTIFIED IN WRITING PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE WELL TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE Production Asst. DATE 8/24/93  
TYPE OR PRINT NAME Donna Williams TELEPHONE NO. 488-6913

(This space for State Use)  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

AUG 26 1993

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: