

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well well
2. NAME OF OPERATOR
CONOCO INC.
3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FNL & 1700' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF

- ☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

JAN 14 1981

U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

C.O. to 6965'. Set RBP 6950', pkr 6750'. Pmp. 3000 gals. NE-FE-HCL. Pmp 400# rock salt in 400 gals. brine. Flush w/TFW. Reset RBP 5900', pkr 5780'. Pmp. 1800 gals. 15% NE-FE-HCL. Pmp 400# rock salt in 400 gals. brine. Flush w/TFW. Reset RBP 5350', pkr. 5250'. Pmp 1500 gals 15% NE-FE-HCL. Pmp. 200# rock salt in 200 gals. brine. Flush w/TFW. Swab back load. Place well on production. Test.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Wm C. Dutton TITLE Administrative Supervisor DATE January 13, 1981

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

USGS
NMP44
FILE

*See Instructions on Reverse Side

APPROVED

JAN 15 1981

DISTRICT SUPERVISOR