

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-031620 b

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

Box 460 Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

990' FNL and 1700' FNL of Sec 12

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3583' df

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Skaggs B

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Skaggs Aquifer

11. SEC., T., R., E., OR BLK. AND SURVEY OR AREA

Sec 12, T-20S, R-37E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☒
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Squeeze Perfs

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to squeeze perfs and stimulate this well by the following procedures. Spot 71 cu. ft (60 SKs) Class C cement w/ 290 bentonite and 3# salt per sock from 6940' to 6660'. Spot sand from top of packer at 6660' to 5900'. Spot 40 sacks Class C cement from 5900' to 5700'. Set packer at 5260'. Treat perfs w/ 3000 gals LSTNE 15% HCL acid.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Admin. Supervisor

DATE

3-27-72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

MAR 28 1972

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

USGS(5) NMFu(4) File