

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Use this form for proposals to drill or to deepen or plug back to a different depth. Use Form 9-331-C for such proposals.)

1. ☒ gas well ☐ other

2. NAME OF OPERATOR
Garcia, Inc.

3. ADDRESS OF OPERATOR
P.O. Box 460, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1880' ~~FWL~~ & 330' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☒

SHOOT OR ACIDIZE ☒

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Drill out pkr, open add'l pay, acid frac

5. LEASE

LC-031621 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

NMEU

8. FARM OR LEASE NAME

Britt B

9. WELL NO.

20

10. FIELD OR WILDCAT NAME

Monument Tubb/Weir Blinebry

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 10 - 20S - 37E

12. COUNTY OR PARISH

Lea

13. STATE

NM

14. API NO.

30-025-20299

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. DO pkr @ 6398'. Spot 3 bbls 15% HCL-NE-FE from 6462' - 6345'. Perf upper Tubb w/ 1 JSDF 6345' - 6462' (total 20 holes). Set RBP @ 6560' & pkr @ 6470'. Acidize lower Tubb w/ 40 bbls 15% HCL-NE-FE & flush w/ 40 bbls TFW. Rls RBP & pkr. Set RBP @ 6480' & pkr @ 6150'. Acidize upper Tubb w/ 30 bbls 15% HCL-NE-FE, flush w/ (ATTACHMENT)

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. A. Burtner

TITLE

Administrative Supervisor

DATE

9/5/84

(This space for Federal or State office use)

Mark Hollis

Area Manager

DATE

1-9-84

DO pkr, Open Add'l pay, Acid frac (Cont'd)

43 bbls TFW. Acid frac upper Tubb w/ 192 bbls .
gelled fluid and 150 bbls 15% HCL-NE-FE acid.
2.0. RL 550' & pk. Set RBP @ 5950' & pkr @ 5500'.
Acidize Blinebry perfe w/ 24 bbls 15% HCL-NE-FE,
flush w/ 42 bbls TFW. Swb. Rls RBP & pkr. Reset RBP
@ 6560' & pkr @ 5500'. Chemically Inhibit Blinebry
& Tubb. Rls RBP & pkr. Run prod. equip. & place
well on test.

RECEIVED

NOV 13 1984

U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION