| DISTRIBUTION | | | | |
|-----------------|-----|--|--|--|
| BANTA PF | | | | |
| FILE | | | | |
| U.S.6.1. | | | | |
| LAND OFFICE | î | | | |
| TRANSPORTER | 011 | | | |
| TRANSPORTEN | | | | |
| PROBATION OFFIC | a | | | |

MT

WB

NEW MEXICO OIL CONSERVATION COMMISSION (Form C-104) Santa Fe, New Mexico Revised 7/1/57

REQUEST FOR (OIL) - (GAS) ALLOWABLE

New Well Recompletion

?.

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gai must be reported on 15.025 psia at 60° Fahrenheit. TEXACO Inc. - P. 0. Box 728 Hobbs. New Mexico. July 10, 196h

| | Comos | W AR ORAN | and a | H. B. Phillips "B", Well No. 1, in. SE 1/4. NW |
|--------------------------|--------------------------|-----------------|---------------------|---|
| | F | , Sec | 10 | T. 20-S, R. 37-E, NMPM., Monument Tubb Pool |
| | Letter | | | |
| | | | | Elevation |
| Pl | lease in | dicate loc | ation: | Top Oil/GAX Pay 65311 Name of Prod. Form. Tubb |
| D | C | B | A | PRODUCING INTERVAL - 6531', 6540', 6548', 6555', 6564', 6591', and 66 |
| E | r x | G | H | Perforations Open HoleNONE Depth 68871 Depth 68871 Casing Shoe Tubing_68871 |
| L | K | J | I | OIL WELL TEST - Choke Natural Prod. Test:bbls.oil,bbls water inhrs,min. Size |
| M | N | 0 | P | Test After Acid or Fracture Treatment (after recovery of volume of oil equal to volume of load oil used): 72 bbls.oil, 1 bbls water in 5 hrs, 0 min. Size 20/ GAS WELL IEST - |
| | | | | |
| ubing (| (Foor Casing | | ing Record | |
| | | Fret | Sax | Test After Acid or Fracture Treatment:MCF/Day; Hours flowed |
| 9 5/8 | 3" 1 | 316 | 700 | Choke SizeMethod cf Testing: |
| 2 7/8 | 3" 6 | 877 | 2000 | Acid or Fracture Treatment (Give amounts of materials used, such as acid, water, oil, and sand): See remarks |
| 15 | 3" 6 | 875 | 2000 | Casing Tubing 340 Date first new July 6, 1964 |
| 2 7/8 | | | | 011 TransporterThe Permian Corporation |
| 2 7/8 | | | | Gas Transporter NONE (To be Connecter Later) |
| emarks | | orate 2 | 2 7/8" 0 | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564', 659 |
| emarks | | orate a | 2 7/8" C ze with | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564', 659 500 gals acetic acid. |
| emarks and 66 | 504 * • | A ci di: | ze with | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564', 659 |
| emarks and 66 I he | 504 1 . | Acidi: | ze with | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564!, 659 |
| emarks and 66 I he | 504 ° . Freby ce d | Acidi: | the infor | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564!, 659 |
| emarks and 66 I he | 504 ° . Freby ce d | Acidi: | the infor | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564!, 659 |
| emarks and 66 I he | 504 ° . Freby ce d | Acidi: | the infor | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564!, 659 500 gals acetic acid. rmation given above is true and complete to the best of my knowledge. 19 |
| emarks and 66 I he | 504 ° . Freby ce d | Acidi: | the infor | Casing with one jet shot at 6531', 6540', 6548', 6555', 6564!, 659 |

I W. E. Morgan being of lawful age and being the Assistant to the Dist. Supt. for TEXACO Inc., do state 20 that the deviation record which appears on this form is true and correct to the best of my knowledge.

W. E. Morgan Subscribed and sworn to before me this day of July _____64 . My commission expires October 20, 1966. . Notary Republic R. E. Johns on Lea County, State of State of New Mexico for Lease E. H. B. Phillips "B" Well No. l Deviation Record Depth Degrees Off 100**1** 1/2 650 1/2 9001 $^{\prime}$ 11251 '2 12761 1/4 16251 1/4 21001 1/4 26601 2 27631 3/4 1 28551 ļ 34801 3/4 37041 3/4 38201 3. 39501 l /2 42001 1/2 469**71** 1 1/4 19601 1 5300**1** 3/4 56151 1 58551 3/4 6050**'** 1/262001 1 63501 1/2 66001 1/26850**'** 2 6890**1** 2