

OIL CONSERVATION DIVISION
P.O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-72

NO. OF TUBING HEADS	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFRACE OR PLUG BACK TO A DIFFERENT DEPTH.
SEE APPLICATION FOR PERMIT WITH FORM C-101 FOR SUCH PROPOSALS.)

1a. ☒ GAS WELL ☐ OTHER	
1b. Name of Operator TEXACO INC.	
1c. Address of Operator P.O. BOX 728, HOBBS, N.M. 88241	
1d. Location of Well G 1980 N 1980 E 10 LINE, SECTION 10 TOWNSHIP 20-S RANGE 37-E	

7. Unit Agreement Name
8. Firm or Lease Name E.H.B. PHILLIPS "B"
9. Well No. 2
10. Field and Name of Wildcat Monument Tubb Skaggs Drinkard
11. County LEA

15. Elevation (Show whether DF, RT, GR, etc.)

3585' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

NEW REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
UNDESIRABLE ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
THIS CALCITE SCALE TREATMENT ☐			

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRUPU, PULL RODS AND PUMP. INSTALL BOP.
2. LOWER 2 1/16" TBG. FROM 6770' TO 6790'.
3. SPOT 600 GAL. 15% NEFE AND 12 GAL. MUTUAL SOLVENT. SI 2 HRS.
4. SWAB BACK LOAD PLUS 20 BBLS. FLUID.
5. PUMP 5 GAL. SURFACTANT W/ 10 BW, 110 GAL. INHIBITOR W/ 25 BW, AND 200 BW AS FLUSH. SI WELL 18 HRS.
6. SET TBG. @ 6770'. TIH W/ PUMP AND RODS. RDP.
7. TEST WELL.

BDB

Eddie W. Seay

Eddie W. Seay
Oil & Gas Inspector

TITLE DIST. OFF. MTL

DATE 11-13-85

NOV 18 1985