

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL OR TO DEEPEN OR TO PLUG BACK TO A DIFFERENT RESERVOIR."

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 031620 (b)	
2. NAME OF OPERATOR Continental Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, New Mexico		7. UNIT AGREEMENT NAME NMPU	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL and 1980' FWL Section 11, T-20 R-37, Lea County, New Mexico, NMPM.		8. FARM OR LEASE NAME Skaggs B A/C 1	
14. PERMIT NO.		9. WELL NO. 6	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3573 GL		10. FIELD AND POOL, OR WILDCAT Monument Tubb Pool	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11-20-37	
		12. COUNTY OR PARISH Lea	
		13. STATE N.M.	

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work was performed on subject well using the following procedures:

TD 6700' Pay: Tubb 6454-6620'. Perfs: 6470', 6560', 6593', 6602', 6606', & 6618' w/1 JSPP/ On latest test 11-26-65 flwd 34 BO, 0 BW in 24 hrs. TP 350#, CP Pkr, 21/64" chk, GOR 16,647. Work done: killed well, set pkr at 6576'. Failed to pump into perfs 6593, 6602, 6606, & 6618' w/4500#. Spotted 250 gals 15% LSTNE acid over perfs Hold w/5000# on perfs for 1 hr. Failed to take fluid. Perfd 6593, 6602, 6606, 6618' w/2 JSPP. Set Pkr at 6570'. Treated perfs w/2500 gals 15% LSTNE acid w/6 ball sealers. After: - Pay Tubb 6454-6620' Perfs 6470, 6473, 6560, 6593, 6602, 6606, 6618' w/2 JSPP. On test 2-8-66 flwd 65 BO, 0 BW, 600 grvty, 823 MCFG, in 24 hrs. TP 835#, CP 275#, 18/64" Chk. GOR 12,661. Workover started: 2-5-66, completed 2-6-66.

18. I hereby certify that the foregoing is true and correct

SIGNED **SIGNED: HAL R. STEPHENS**TITLE **Staff Supervisor**DATE **3-14-66**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

USGS-5, ATL ROS-2, PAN AM HOBBS-3, CALIF MID-2 LPT

*See Instructions on Reverse Side

MAP 10 1966

J. L. GARDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

MAR 55 11 08 AM '66
HORDS OFFICE O.C.C.