omit 3 Coples Appropriate strict Office . \*

LW

.

DISTRICT   OIL CONSERVA	TION DIVISION		
P.O. Box 1980, Hobbs, NM 88240 <u>2040</u> Pacheco St. <u>DISTRICT II</u> Santa Fe, NM 87505		WELL API NO.	
		30-025-21491	
P.O. Drawer DD, Artesia, NM 88210		sIndicate Type of Le	base
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410		State Oil & Gas Le	ase No.
SUNDRY NOTICES AND REPORTS ON			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7Lease Name or Un	nit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)		E. O. CARSON	1
Type of Wett:		-	
OIL GAS WELL OTHER			
Name of Operator		«Well No.	······································
TITAN RÉSOURCES I, INC.		23	
		Pool name or Wild	
500 W. TEXAS, SUITE 500, MIDLAND, TX 79701		EUMONT; YA	TES-7 RIVERS-QUEEN
Well Location	00.40		
Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u>	Line and2340	Feet From The	WEST Line
Section 33 Townshin 21S			
Section 33 Township 21S	Range 37E	NMPM	LEA County
3459 GR.	r Di=, RRD, RT, GR, Bic.)		
Check Appropriate Box to indicate	Nature of Notice, Re	eport, or Other	Data
NOTICE OF INTENTION TO:	SUB	SEQUENT R	EPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK		
			ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS		OPNS.	PLUG AND ANBANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEN	IENT JOB	
OTHER:	OTHER: Test San A	ndres and Abando	n Queen Sand
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and	d alve pertinent dates, including e	stimated date of startin	any proposid
work) SEE RULE 1103.	•		g, proposid
Queen Sand perfs 3481ft to 3519 ft.			
5/24/97 MIRU pulling unit. NU BOP & POOH with tubing. RIH with	h clean-out bailer and bit.	Fagged fill at 3436	ft. Cleaned out to 3792 ft
5/28/97 Cleaned out to 3902 ft. POOH & LD bailer. RIH with casi 5/29/97 RU wireline truck and perforated San Andres with 1 shot	1g scraper to 38/5 π. #t from 38/0' to 385/' ( 15	holes) PILL with p	ooker and tubing. Cot neeker
at 3780 ft. RU swab and swabbed dry.	11 1011 3040 10 3034 ( 15	noies). Kin with p	acker and lubing. Set packer
5/30/97 Acidized perfs 3840' to 3854' with 1,500 gal 15% NEFe I	ICI. RU swab and swabbe	d back load water.	
5/31/97 Swabbed and flow tested.			
6/01/97 Testing 6/04/97 Ran pump and rods and put on production.			
6/05/97 Pumped 24 hours; made 9 bbl oil, 55 bbl water, and 67 r	ncf.		
6/06/97 Pumping and testing.			
6/07/97 MIRU pulling unit. POOH with rods and pump			
6/08/97 POOH with tubing. RIH with sand bailer and cleaned out at 3780 ft. RU swab and swabbed well down.	20 IT OF THE POOH and LD	baller. RIH with pa	cker and tubing. Set packer
6/10/97 SITP 900 psi. Bled off pressure and swabbed well down.	POOH with packer. RIH w	ith retrievable brid	ge plug and packer. Set BP
at 3505, packer set at 3340 ft. Squeezed Queen Sa	nd perfs 3481' to 3519' wit	h 137 sx cement. (	Queen Sand abandoned.
3585			
I hereby certify that the information above is true and complete to the best of my kr	owledge and belief.		
SIGNATURE // MA A A	TITLE PRODUCTION OPER	ATIONS MANAGER	DATE 06-15-97
the second secon			
TYPE OR PRINT NAME BRUCE WOODARD			TELEPHONE: NO. 915/682-6612
(This space for State Lise)			
			'UN 18 199
		٨	-
APPROVED BY	TITLE		DATE
CONDITIONS OF APPROVAL, IF ANY:			
CONDITIONS OF APPROVAL, IF ANT:			
	ZA ELINA	IT VATER -	RVRS QUEEN