

CO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC
1-file

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator GENTRY OIL COMPANY		8. Farm or Lease Name S. J. SARKIS	
3. Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO 88240		9. Well No. 6	
4. Location of Well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>NORTH</u> LINE AND <u>2310</u> FEET FROM THE <u>LINE</u> LINE, SECTION <u>20</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat DRINKARD	
15. Elevation (Show whether DF, RT, GR, etc.) 3381 GR		12. County LEA	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is presently completed in Wantz Abo (6784-7273') producing 7 BOED and 35 MCFPD.

For partially abandon Wantz Abo with Model "B" Packer and Drinkard plug set at 67-0' (+).

Perforate Drinkard from 6388 to 6632; (29 holes). Top of Drinkard @ 6386'.

Acidize and frac same interval.

Complete Drinkard zone with one string of 2-3/8" tubing and packer.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL

SIGNED C.L. Wade C. L. Wade TITLE AREA SUPERINTENDENT DATE 1-15-75

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

HR/bh

RECEIVED

JAN 16 1975

OIL CONSERVATION COMM.
HOBBS, N. M.