

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22852
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Royalty Holding
2. Name of Operator American Exploration Company	8. Well No. 2
3. Address of Operator 1331 Lamar, Suite 900 - Houston, TX 77010	9. Pool name or Wildcat Blinebry & Wantz Abo
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>East</u> Line and <u>1980</u> Feet From The <u>North</u> Line Section <u>25</u> Township <u>21S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/3/96 50 Sks cement at 4400'; Tag at 4360'.
12/3/96 25 sks cement at 3500'.
12/3/96 25 sks cement at 2900'.
12/3/96 50 sks cement at 915'; Tag plug at 612.
12/4/96 10 sks cment from 30' to surface

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charley Gregg TITLE President DATE 12/6/96

TYPE OR PRINT NAME Charley Gregg - SNG Well P&A Services, LLC TELEPHONE NO 915/570-7685

(This space for State Use)
APPROVED BY Charles Lerrin TITLE OIL & GAS INSPECTOR DATE Jan 11 1997

CONDITIONS OF APPROVAL, IF ANY: