

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator IMPERIAL AMERICAN MANAGEMENT COMPANY		8. Farm or Lease Name Royalty Holding	
3. Address of Operator 215 Mid America Building, Midland, Texas 79701		9. Well No. 3	
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East LINE, SECTION 25 TOWNSHIP 21S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Drinkard	
15. Elevation (Show whether DF, RT, GR, etc.) 3406 GR		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Status Report

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well T/A 8-22-69 as non commercial from this zone; evaluation of workover procedure was anticipated.

Expires 11/1/75

The ownership of this property is in reorganization under Chapter X of the Federal Bankruptcy Act. The Trustee of the corporation has not been able to provide funds for the necessary examination of workover potential. It is anticipated that the company's reorganization will be complete in the latter quarter of 1975 and that funds will then be available to examine the property for workover possibilities and to perform the workover if justified. We request that adequate time be given for this contingency prior to the forced plugging and abandonment of the well. The lease is being held by production from the Royalty Holding Well No. 1, and there is no danger of losing the lease.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 10/26/74

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: