

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

L. C. 062170 (B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

Imperial-American Management Company

3. ADDRESS OF OPERATOR

507 Midland Savings Bldg.-Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660 FWL & 1980 FNL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sam Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 7 T. - 21 S. R. - 38 E.

12. COUNTY OR PARISH 13. STATE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3506 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒ Temporarily AbandonedREPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

I. Well was temporarily abandoned on April 25, 1969.

II. Well was T. & A. due to inability to obtain commercial production.

III. Method of abandonment- Set cement retainer at 5998' & Squeezed perfs- 6016 to
6325 W/150 sx Class C- did not drill out. Pulled tubing & Suspended operations.

IV. Perforated Intervals open in the well bore-

Abo - open hole 7499-7530'

perfs - 7358- 7498'

Casing collapsed @ 7237'. unable to recover RTTS tool set @ 7266'. Set retrievable
bridge plug @ 6350 & Squeezed Blinbry perfs- 6016-6325, did not drill out or recover
retrievable bridge plug.

18. I hereby certify that the foregoing is true and correct

SIGNED Daniel K. KoneyTITLE Area ManagerDATE 2-5-70

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

FEB 9 1970

*See Instructions on Reverse Side U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO