

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	30-025-23117
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	W.T. MCCOMACK
8. Well No.	17
9. Pool name or Wildcat	BLINEBRY OIL & GAS
10. Elevation(Show whether DF, RKB, RT, GR, etc.)	3459 GL

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	4. Well Location Unit Letter <u>I</u> : <u>1930</u> Feet From The <u>SOUTH</u> Line and <u>990</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

<b>NOTICE OF INTENTION TO:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

<b>SUBSEQUENT REPORT OF:</b>	
REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <u>PLUG BACK, PERF, ACDZ</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, POOH W/ PROD. EQUIP.  
SET CIBP AT 6000', DUMP 35' CMT. ON TOP OF CIBP.  
TOC AT 5965', NEW PBTD.  
PERF BLINEBRY AT 5436'-5590'. W/ 4" GUNS, 0 DEG. PHSD.  
TOTAL OF 31 HOLES, 1 JHPF.  
ACDZ PERFS W/ 4800 GALS, 15% NEFE.  
SWB/TST PERFS.  
FRAC PERFS 5436'-5590' W/ 36,000 GALS GEL.& 83,500 # SAND. SWB/TST.  
TIH W PROD. EQUIP, EOT AT 5401'.  
RETURN TO PRODUCTION.  
WORK BEGAN 9-5-91 WORK ENDED 9-13-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<u>P.R. Matthews</u>	TITLE	TECH. ASSISTANT
DATE:		9-16-91	
TYPE OR PRINT NAME	P.R. MATTHEWS		TELEPHONE NO. (915)687-7812
APPROVED BY		TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:			

24 Feb 1991