


that the tests indicate that the well is not capable of commercial production.

If you need any further aid in connection with this matter please advise us.

Sincerely yours,

HINKLE, COX, EATON,
COFFIELD & HENSLEY



C. D. Martin

CDM:cm

xc: Joe Steely
Production Coordinator
Cleary Petroleum Corporation
Broadway Executive Park
6501 N. Broadway
Oklahoma City, Oklahoma 73116

Don W. Erickson
Cleary Petroleum Corporation
Broadway Executive Park
6501 N. Broadway
Oklahoma City, Oklahoma 73116

D. S. Nutter
Chief Engineer
New Mexico Oil Conservation Commission
Post Office Box 2088
Santa Fe, New Mexico 87501

RECEIVED

FEB 7 1978

OIL CONSERVATION COMM.
HOBBS, N. M.