

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
WITH ORIGINAL
AND TWO COPIES

TE
re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Warren Unit
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 33
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit F	10. FIELD AND POOL, OR WILDCAT Blinebry Oil & Gas/Warren Tu
14. PERMIT NO. 1980' FNL & 1980' FWL 30-025-25044	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 27-20S-38E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANE ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ Downhole commingle & acidize	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU on 10-29-86. Unseat both pumps. POOH w/ Blinebry tbg.
- ② POOH w/ vent string & long string. POOH w/ pkr. Ran scraper to 6875.
- ③ Set RBP @ 6710' & pkr @ 6467'. Acidized Tubb w/ 35 bbls 15% HCL & xylene (75%/25% mix). Flushed w/ 34 bbls TFW. Reset RBP @ 6450' & pkr @ 5833'. Acidized Blinebry w/ 65 bbls 15% HCL & xylene (75%/25% mix). Flushed w/ 35 bbls TFW. Swab.
- ④ Gilt w/ production string. Test pumped 41 BO, 10 BW, 162 MCF on 11-18-86.

ACCEPTED FOR RECORD

JAN 07 1987

Jm

CARLSBAD NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED De Finney DE FINNEY

TITLE Administrative Supervisor

DATE 12-18-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side