O. OF COPIES RECEIVED DISTRIBUTION		Form C-103 Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
u.s.g.s.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Oil & Gas Lease No.
SUN (DO NOT USE THIS FORM FOR USE "APPLI		
OIL X WELL MELL	OTHER-	7. Unit Agreement Name
2, Name of Operator	8. Farm or Lease Name	
Amerada hess Cor	Cill Deep	
3. Address of Operator P.O. Box 2040, T	9. Well No.	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER	700 FEET FROM THE South LINE AND 1889 FEET FR	-Drinkard/Blinebr
	CTION 31 TOWNSHIP 215 RANGE 37E NM	PM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12, County
Gr. 3464 ¹		lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		
NOTICE OF	* INITENITION TO	Other Data INT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB IN	ALOG AND ABANDONMENT
Danifornita and a	OTHER	
OTHER TOTALOTHEO MEICH S	sand/water frac.	
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed
6,800' TD by drille	r, 6,7991 TD by Loggers	
of 6,800' @ 8:45 AM 6797 to 1050' and G 7"0D 23 & 26# N-80 wate cement by Hall	9-5/8"OD csg. (Ro: Sundry Notice report dated Dec 12/30/75, cond. hole and logged with Schlumberg R to surface, dual laterolog 6780 to 4100' 12/31 and K-55 new casing at 6798' with total of 1950 iburton in 2 stages, cement circ. on 2nd stage at Cactus Drlg. Co. 1/1/76	ger CNFD W/GR & caliper - 1/75, run, set and cemented of sx. expanding and lite
Moved and rigged up cellar 3960 to 3963 1/6/76, tested 0.K.	λ & S completion unit $1/5/76$, FIH with bit and ', TlH and circ. hole clean 0 6669' and tested 7	drilled out plug and D.V. 7" csg. with 1500# PP
bleed press. off re After testing Drink	nd acidize Drinkard oil zone different intervals set packers Sd/wtr. frac Drinkard perfs. and to ard zone, reset and perforate Blinebry oil zone ize same, bleed off press., reset packer and same e for production	est same for production.
18. I hereby certify that the information	title Supervisor Tech/Drlg. Adv.	ı. Ser _{ere} Jan. 8, 1976

ierry Sendon Usa I. Supr.

RECEVED

AN 1 1 1976

EL CONSERVATION COMM. HOBBS. N. M.