## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. OF COPIES ACCEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE		
U.3.0.5.	1	_
LAND OFFICE		
OPERATOR	1	-

## OIL CONSERVATION DIVISION

DISTRIBUTION	10 22 10 N	
BANTA FE	P. O. BOX 2088	Form C-103
FILE	SANTA FE, NEW MEXICO 87501	Revised 10
U.3.0.5,		So Indiana T
LAND OFFICE		5a. Indicate Type of Lease
OPERATOR		State Fee
		5. State Oil & Gas Lease No.
CLINI	DDV NOTICE	
NUC NOT DEL THE POR TOR OUT	DRY NOTICES AND REPORTS ON WELLS	mmmmmmmm
USE "APPLI	CATION FOR PERMIT = " (FORM C-101) FOR SUCH PROPOSALS.)	(
01L [V] 6A9 [		
WELL (A) WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		
Marathon Oil Co	OMBonz	8. Farm or Lease Name
J. Address of Operator		No. 1 o
1		Mark Owen
P.O. Box 2409, Hobbs, New Mexico 88240		_
4. Location of Well	00240	7
North	660	10. Field and Pool, or Wildcat
	660 FEET FROM THE South LINE AND 2310	PEET FROM Wantz Abo
West		THE THE WAY TO SEE THE WAY THE WAY TO SEE THE WAY TO SEE THE WAY THE WAY TO SEE THE WAY TO SEE THE WAY TO SEE THE WAY THE WAY THE WAY THE WAY THE WAY TO SE
THE LINE, SEC	TION 35 TOWNSHIP 21S RANGE 37E	
tummin		— нмэм. <b>////////////////////////////////////</b>
	15. Elevation (Show whether DF, RT, GR, etc.)	
		12. County
16.		Lea
Check	Appropriate Box To Indicate Nature of Notice, Repo	
- NOTICE OF I	INTENTION TO:	rt or Other Data
·	Subs	EQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	PLUG AND ABAHDON REMEDIAL WORK	ALTERNA
	COMMENCE DRILLING OPHS.	- ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	OTHER Temporar	ily Shut-In
OTHER		rry Shut-In
17. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates,	
DANY SEE HOLE 1103.	personent details, and give pertinent dates,	including estimated date of starting any propose
_	•	
On May 14, the W	antz Abo was treated with 10,000 gal	
acid. The well	Was the was treated with 10,000 gal	lons of 15% crosslinked
it was doorded to	was then swab tested and it produced o temporarily abandon the War	no fluid where
Crasic was decided t	o temporarily abandon the Wantz Abo e below this will be reactions.	no fluid. Therefore
Granite Wash zon	e below this will be reactivated.	formation. The Wantz
	- "LLI be leactivated.	
		•
	. •	•
		•
		•
		•
•		
	•	
•	•	·
		•
. I hereby certify that the information at	boye is true and complete to the best of my knowledge and belief.	
1/2 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1	Z anowledge and belief.	,
Man - Charles	<del></del>	
Thom.	as F. Zapatka Production Enginee	<b>-</b>
	Enginee	r June 1, 1984
OBIOINAL TO		1 June 1, 1984
OKIGHNAL STANES OF I	EBBV CEVEA.	1, 1984
ORIGINAL SIGNED BY JI DISTRICT I SUPPR	ERRY SEXTON	JUN 4. 1984

HOBBS OFFICE