
UNITED STATES DEPARTMENT OF THE INTERIOR

| 5. LEASE LC-063458 | |
|-----------------------|--|
| | |

| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different | 7. UNIT AGREEMENT NAME |
| reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME |
| 1. oil gas well other | 9. WELL NO. |
| 2. NAME OF OPERATOR | 38 |
| COTTINENTS OF COMPANY 3. ADDRESS OF OPERATOR, 11 | 10. FIELD OR WILDCAT NAME WARREN BLINEBRY |
| Box 460, Hobbs N.M. 88240 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | AREA 7 205 P 395 |
| below.) AT SURFACE: 1980 FNL + 1980 FWL | 50c. 34, 7-205, R-38E 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: Samp | Lod N.M. |
| AT TOTAL DEPTH: 530 0. | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | 15 FLEVATIONS (CHOW DE KED AND WE) |
| | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | |
| EDACTURE TREAT | NUCLOS AND SERVICE OF THE PROPERTY OF THE PROP |
| SHOOT OR ACIDIZE | 事及是 以 。 |
| PULL OR ALTER CASING TO THE PURISHER COMPLETE TO THE PROPERTY OF THE PURISH TO THE PURISH THE PURIS | (NOTE: Report results of multiple completion or zone change on Form 9–330.) |
| MOLITICE COMILECTE | OCHEV . |
| ABANDON* 2 / 1 U. S. GEOLO | EM WEXICO |
| (other) Ro-Port Blindry X HO3BS. | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly star including estimated date of starting any proposed work. If well is a | te all pertinent details, and give pertinent dates, |
| measured and true vertical depths for all markers and zones pertine | nt to this work.)* |
| IT 15 Proposed to Ro-Porforate | The Blinebry soction of |
| The subject well be couse of | 3 (9/014m 24/8546 200 V |
| build 4P. | |
| 1. hord The well with Tracked Free | + 1/22 |
| 2. Pull Prod. Equip and cloon out | 10-8000 |
| 3. Po. f. Q 5806, 17, 31, 35, 38, 48,52 41, 43, 47, W/2TSPF | 3,66,69, 75,80,92,5938, |
| 41, 43, 47, W/2TSPE | |
| 4. Ro. Run 23/8 Prod. The Sof 24. | I 5770 and FAIRING NIPPLO 27 |
| 75940'. | |
| 5. Roturn the well to Production | |
| Subsurface Safety Valve: Manu. and Type | Set @ Ft. |
| 18. I hereby certify that the foregoing is true and correct | |
| SIGNED WM. Q. Kutterfiel TITLE ADMIN. SC | MY. DATE 4-3-18 |

(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

USG5(5), NMFU(4), F, 1e



|