

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well ☐ Oil Well ☐ Gas Well ☒ Other INJECTION	7. If Unit or C.A. Agreement Designation
2. Name of Operator Conoco Inc.	8. Well Name and No. WARREN UN BLIN/TUBB #41
3. Address and Telephone No. 10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424	9. API Well No. 30-025-25245
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' ^{SSS} 660' FSL & 660' FWL, SEC. 27, T-20S, R-38E, UNIT LTR 'N'	10. Field and Pool, or Exploratory Area WARREN BLINE/TUBB
	11. County or Parish, State LEA, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☒ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Perforation Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6-15-92 MIRU. POOH W/ RODS, PUMP & TBG. KILLED WELL WITH 70 BBLs 9.0# BRINE.
RIH W/ BIT & SCRAPER TO 5615', C/O TO PBTD @ 6868'. POOH.
RIH W/ RBP & PKR. SET RBP @ 6657', PKR @ 6578'. PUMP 90 BBLs WTR TO CHECK CSG FOR
COMMUNICATION - NONE. POOH. RIH W/ CMT RET TO 6480'. MIX & PUMP 100 SX CLASS H W/ 2%
CACL2 & CELLOFLAKE FOLLOWED W/ 100 SX CLASS H W/ 2% CACL2. PUMP 106 SX BELOW RETAINER,
PRESSURE UP ON SQUEEZE, PULL OUT OF RETAINER. POOH.
RIH W/ BIT & 6 DRILL COLLARS TAG CMT @ 5960'. DO CMT TO 6640', CLEAN OUT TO 6868'. POOH.
RIH W/ PERF GUN 1 JSPF PERF TUBB @ 6566-89, 6600-08, 6613-23, 6643-46, 6650-52.
PERF BLINEBRY @ 5932-38, 5941-43, 5950-54, 5980-82, 5986-89, 5991-94, 6000-03, 6007-13,
6018-22, 6025-28, 6045-47, 6055-57, 6126-28, 6130-33, 6143-48, 6151-55, 6161-69, 6175-78.
RIH W/ PKR @ 5800'. BREAKDOWN PERFS W/ 5000 gal 15% NEFE HCL. POOH.
RIH W/ TBG & INJECTION PACKER, SET @ 5792'. TEST CSG TO 500# FOR 30 MIN - HELD.
RDMO.
PLACED WELL ON INJECTION 7-9-92.

ORDER NO R-6906-B AUTHORISED THIS WELL TO BE CONVERTED TO INJECTION.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title SR. REGULATORY SPEC.

Date 7-17-92

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

SSS

10 GW A N
P-6906 B

