

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYCOPY TO O.G.C.  
SUBMIT IN TRIPPLICATE\*  
(Other instructions on  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-063458

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR

Box 460, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FSL &amp; 660' FWL OF SEC. 26

7. UNIT AGREEMENT NAME

WARREN

8. FARM OR LEASE NAME

WARREN UNIT

9. WELL NO.

44

10. FIELD AND POOL, OR WILDCAT

WARREN Blimbry-Tubb

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 26 T. 20S R. 38E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3551' GR

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON\* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT\* ☐(Other) ☒Set Production Gg  
(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

DRLD 8 3/4" Hole From 1553' To 7007' TD (Loggers TD).  
Set 7" CSG AT 7000' and CMTD IN 2. Stages with  
DV Tool Set AT 3993'. 1st Stage Pumped 400 SX class "C"  
CMT. Plug Down AT 6:00 AM 3-2-77. Opened DV Tool and  
Circ. 4 Hrs. 2nd Stage Pumped. 1100 SX class "C" CMT  
with Additives. Plug Down AT 11:30 AM 3-3-77. TOP OF  
CMT AT 400'. Released Rig 3-3-77. W.O. Completion  
Rig.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Wm. J. Hester

TITLE

Admin. Supv.

DATE

3-8-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 10 1977

U.S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

\*See Instructions on Reverse Side

USGS(5), NMFL Partners (4), F.