## STATE OF NEW MEXICO GERGY AND MINERALS DEPARTMENT

we. or conice accoives		
DISTRIBUTION		
BANTA FE		
FILE	<b>†</b>	
U.S.O.S.		
LAND OFFICE	1	
OPERATOR	<del>                                     </del>	

## OIL CONSERVATION DIVISION

DISTRIBUTION	P O 90	Y 2000	_
BANTAFE	P. O. BOX 2088 SANTA FE, NEW MEXICO 87501		Form C-103
FILE	SANTA FE, NEW	/ MEXICO 87501	Revised 10-1-7
U.S.O.S.			5a. Indicate Type of Lease
LAND OFFICE			
OPERATOR			State Fee X
<u> </u>			5, State Oil & Gas Lease No.
SUNDRY	NOTICES AND REPORTS ON SALS TO DAILL ON TO DEEPEN OF PLUE B	WELLS	mmmmmm
USE "APPLICATION	DSALS TO DRILL OR TO DECPEN OR PLUG B N FOR PERMIT - " (FORM C-101) FOR SUC	ACK TO A DIFFERENT RESERVOIR.	
<u></u>	- Voly row age	H PROPOSALS.)	
OIL GAS WELL			7. Unit Agreement Name
Name of Operator Brine Well		G.P. Sims	
Grima N.O. 7	O + I	11 /)	8. Farm of Lease Name
Sims McCasland Water St	ation Estate of	7 D. P. Min si	) 2
Notices of Operator		- June	9. Well No.
PO Box 98 Eunice, NM	88231		s. wen No.
Location of Well			
Α 42	0		10. Field and Pool, or Wildcat
UNIT LETTER 42	O FEET FROM THE North	LINE AND 210 FEET FROM	
	•		mmmmmmm,
THE LINE, SECTION_	32 - TOWNSHIP 21	HANGE 37	
		MANGE UT NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)			
		7. , K1, OK, etc.)	12. County
	7777		L Lea \\\\\\\\
Check Ap	propriate Box To Indicate Na	ature of Notice, Report or Oth	D
NOTICE OF INT	ENTION TO:	Supersured	ier Data
·	1	PURSEQUENT	REPORT OF:
REFORM REMEDIAL WORK		<del></del>	
MPORARILY ABANDON	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
<del></del>		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
LL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	- A DANG GRAZAT
		OTHER	
OTHER			
Describe Proposed or Completed Operat	ions (Clearly state all pertinent detail	ls, and give pertinent dates including	estimated date of starting any proposed
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		o , meraling	estimated date of starting any proposed
Diagod	_		
kinadea nb balli	1g unit on 12/26/81. Pi	ull tubing out of	•
tubing parted a	t 1243', run hit and tul	ull tubing out of well,	tound
	, an ore and tur	ull tubing out of well, bing to 1441' through sa	It section.

Operations Manager 1/4/82