State of New-Mexico Submit 3 Copies Form C-103 Ener Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 OIL CONSERVATION DIVISION **DISTRICT 1** WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 25617 30-025-26505 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE L DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. LG-1207 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: Getty 2 State WELL X WELL COHER 2. Name of Operator 8. Well No. Mitchell Energy Corporation 3. Address of Operator 9. Pool name or Wildcat Maly P.O. Box 4000 The Woodlands, TX 77387-4000 E. Grama Ridge (MULTOW) 4. Well Location 1980 Unit Letter _F : 1980 Feet From The West North Line and Feet From The Line Township 22S Range 34E Lea Section **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2608' G.R. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Blew well down & killed w/45 Bbls 10# Brine. POOH w/tbg & set 35 sx 4/21/92 Cl.H cmt plug @ 11,350'. Set CIBP @ 7950' & dumped 30' cmt on top. Perforated Delaware from 5911-36'. 4/22/92 RIH w/RTTS & acidized zone w/2500 gal 15% NEFE dropping 39 ball sealers. 4/23/92 Flowed back 11 BW & RU swab. Rec 38 BW in 14 runs. Swabbed 119 BW - no show of oil. POOH w/tbg & RTTS. RIH w/192 jts tbg 4/24-28 & SI. POOH w/tbg. Set CIBP @ 5625' w/25 sx cmt on top. Spot 100 sx cmt plug 6/12/92 @ 1600'. POOH & LD tbg. Bled pressure off 10 3/4" annulus. Cut off wellhead. Spot 10 sx surf 6/16/92 plug. Filled cellar & erected P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIONATURE James Blows TITLE Engineer DATE 10-26-92

TYPE OR PRINT NAME James Blount TELEPHONE NO.

(This space for State Use)

APPROVED BY OMY W. Lill

TITLE -

CONDITIONS OF AFFROVAL, IF ANY:

M