Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Edvision 1625 N. French Dr. Hobbs, NM 88240

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. LC-030132(b)

LC-030132(b)
6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals

SUBA	7. If Unit or CA, Agreement Designation		
1. Type of Well Oil Well Well Well Other	 	9 Wally	
2. Name of Operator	8. Well Name and No. CITIES FEDERAL #3		
SOUTHWEST ROYALTIES, INC. 3. Address and Telephone No. P.O. BOY 11320: MIDLAND, TEXAS, 707	9. API Well No. 30 025 26088		
P.O. BOX 11390; MIDLAND, TEXAS 797 4. Location of Well (Footage, Sec., T., R., M., or Survey	10. Field and Pool, or Exploratory Area JALMAT 11. County or Parish, State LEA COUNTY, NM		
330' FNL & 2310' FWL, Unit C, SEC 20, 7			
12. CHECK APPROPRIATE BOX	X(s) TO INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF AC		
X Notice of Intent	Abandonment	Change of Plans	
Subsequent Report Final Abandonment Notice	Recompletion Plugging Back	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water	
	Casing Repair Altering Casing Other stimulate existing zone		
		(Note: Report results of multiple completion on Well	

- 13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)*
- 1) MIRU WS. POH w/production equipment. RU WL.
- 2) Perforate & reperforate Yates Zone from 3,158-3,336'.
- 3) Open perforations w/15% HCl acid.
- 4) Fracture stimulate old & new Yates perfs w/588 bbls. gelled KCl wtr w/93 tons CO2 and 150,500 lbs sd.
- 5) Return well to production.

			=		
14. I heret	by certify th	the forego	ing is true	and gomech	-
Signed	2/	7/97	5 2_		
This	PIG F	rator State	flice hee	(IDLE)	~
Approper	ъy .	/ WAI	HUG	URLEY	
1 Distriction	s of appro	ai, ir any:			

Title AREA SUPERVISOR

Title PE

Date 09/21/00

Date SEP 2.7.2000