Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

N.M. GIL CONS. COMMISSION BOY 1980

4.0. bv	A 174		A OPER A PPR	OVED
HOBBS.	NEW	WEXICO	Bouget Bureau No.	1004-013
,,		i i		

Expires:	31, 1993	J
	Serial No	

BUREAU OF LAND MANAGEMENT	5. Lease Designation and Seria
	IC OCOAEC

	5. Lease Designation and Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS	LC 0634580	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
Type of Well XIX Oil Gas Well Other	8. Well Name and No.	
Name of Operator Conoco Inc.	WARREN UN BLINE-TUB WF #5 9. API Well No. 30-025-26246 10. Field and Pool, or Exploratory Area WARREN BLINEBRY-TUBB 11. County or Parish, State	
Address and Telephone No. O Desta Drive STE 100W, Midland, TX 79705 (915)686-5424		
Location of Well (Footage, Sec., T., R., M., or Survey Description)		
980' FSL & 660' FEL. SEC. 26, T-20S, R-38E, UNIT LTR 'I'		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent Abandonment Recompletion Plugging Back	Change of Plans New Construction Nos-Routine Fracturing	
Final Abandonment Notice Casing Repair Altering Casing Other	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
1-27-93 MIRU. POOH W/ EQUIPMENT. GIH TAG CIBP @ 5980', SPOT 150 SIBP. PUH TO 5536' SPOT 25 SX PLUG OF CLASS C CMT JH TO 4031' SPOT 25 SX PLUG OF CLASS C CMT. PUH TO 3686' SPOT 25 SIPH TO 1360' SPOT 25 SX PLUG OF CLASS C CMT. SPOT 35 SX CLASS C CMT WINTALL P&A MARKER. 1-29-25 RDMO.		
	RECEIV Feb 10 11 17 CARCALLA LA	
Approved as to plugging of the well bore.	[T]	
	19 P	