N. M. CH. CONS. COMMISSION

P. O. BOX 1980

OIL & GAS

U.S. GEOLOGICAL SURVEY

Form 9-331 Dec. 1973

HOBBS, NEW MEXICO 88240

5. LEASE

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

(Do not use this form for proposals to drill onto deepen or plug back to a reservoir. Use Form 9-331-C for such proposals!)

well

AT TOP PROD. INTERVAL:

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

AT SURFACE: 1980'FUL & 1980'FWL

2. NAME OF OPERATOR

CONOCO INC.

LC-063458
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME NHFU
8. FARM OR LEASE NAME
Warren Unit
9. WELL NO.
75
10. FIELD OR WILDCAT NAME
Blinely
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec.34, T-205, R-38E
12. COUNTY OR PARISH 13. STATE
Lea NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CO to 6083! Set ptr @ 5650! Acidize Blinebry perfs
W726615 15% HCL-NE-FE. Flush to top perf w256615 TFW.
Release ptr and pull ptr up to 5200'& circulate ptr fluid
to surface. Set ptr @ 5200! Install injection wellhead &
turn to injection. Verbal approval per Armando Lopez on 10-28-82.
See attached WF Division Order.

Subsurface Safety Valve: Manu. and Typ	p e	Set @	Ft.
18. I hereby certify that the foregoing is	/	Supervisor DATE 1/0 - 2808245	
SIGNED	(This space for Federal or Sta	,TROVE	0
APPROVED BY	TITLE	ANOV 2 1982 ANOV 2 1982 ANOTHER A. GILLHAM DISTRICT SUPERVISO	2 u
:		DISTRICT SUPERVISO	פר

RECEIVED

NOV 4 1982

C.C.D. HOBBS OFFICE