OSPHIBATION NEW MENTCO OIL CONSERVATION COMMISSION SUBSTITUTE THE STATE OF THE MENT OF T	N . OF COPIES ACCEIVED				Form C-103	•	
NEW MENICO OIL CONSERVATION COMMISSION Solid Content Type of Lease Solid Free Free Solid Free Free Solid Free Free Solid Free	DISTRIBUTION					Supersedes Old C-102 and C-103	
SUNDAY NOTICES AND REPORTS ON WELLS SUNDAY NOTICES AND REPORTS ON WELLS SUNDAY NOTICES AND REPORTS ON WELLS PARK TO SURVEY WITH THE PROPERTY OF THE PROPERT	SANTA FE	NE	W MEXICO OIL CONS	ERVATION COMMISSION			
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES OF THE METHOD TO: SUBSTITUTE OF THE METHOD	FILE						
SUNDRY NOTICES AND REPORTS ON WELLS BOOK STATE OF THE ST	U.S.G.S.						
SUNDRY NOTICES AND REPORTS ON WELLS Sunday Sunday Notices Sunday	LAND OFFICE						
Process of the control of the contro	OPERATOR				5, State Oil & Gas	, Lease No.	
The control of the co					mmm	mmm	
Amoco Production Company Amoco Production Company 7. Additional Cyclester P. O. 80x 68x, Hobbs, NM 88240 3. 10. Frest and People of Widerst With Certified A 660 reception to North the Company 10. Frest and People of Widerst The East the Section 12 township 20-5 the Company 3569 GR Check Appropriate Box To Indicate Nature of Nortice, Report of Other Data Substitution of West Nortice of Internation To: **Company 10. Frest and People of Widerst Piper, RT. GR. etc.) **Company 10. Frest and People of Widerst Piper, RT. GR. etc.) **Company 10. Frest Nortice of N	(00 HOT USC THIS FO	SUNDRY NOTICES	AND REPORTS ON	WELLS ACK TO A DIFFERENT RESERVOIR. H PHOPOSACS.)			
Among Production Company Among Production Company Aptended of Come B.	. OIL X 645	OTHER+			7. Unit Alfreement	14dine	
P. O. Box 68, Hobbs, NM 88240 Johnston of Will Johnston of Will Johnston of William Johnston of Willi					8. Farm of Lease	8. Farm of Lease Name	
P. O. Box 68, Hobbs, NM 88240 1. Location of Self THE East Line, Section 12 Township (Show whether UF, RT, CR, etc.) 15. Elevation (Show whether UF, RT, CR, etc.) 15. Section (Show whether UF, RT, CR, etc.) 16. Field and Fool, or Whitecast 17. Section (Show whether UF, RT, CR, etc.) 18. Subsequent report of Other Data 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether UF, RT, CR, etc.) 18. Subsequent report of Constellation (Show whether	Amoco Production Company						
Location of Well					9, Well 110.		
The East and, section 12 ** formatine 20-S ** same 38-E *	P. O. Box 68, 1	lobbs, NM 88240			3	1 - Wildest	
East the section 12 township 20-S same 38-E source 38-				•			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: ***EXPORM MEMORIAL MORE *****PAGE AND ABANDON COMPLETE INTENTION TO: ******PAGE AND ABANDON COMPLETE INTENTION TO: *******PAGE AND ABANDON COMPLETE INTENTION TO: *******PAGE AND ABANDON COMPLETE INTENTION TO: ************PAGE AND ABANDON COMPLETE INTENTION TO INTENTI	UNIT LETTER A	. 660	T FROM THE North	LINE AND 660FEET	FROM House Dri	ikard TITT	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: **CUEDANT NOTICE OF INT	East L	INE, SECTION 12	TOWNSHIP20-	S RANGE 38-E	MPM.		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: ***CLUB ALLEVAND MOUNT SUBSEQUENT REPORT OF: ***CLUB ALLEVAND MOUNT SUBSEQUENT	mmmm	MMM 15.	Elevation (Show whether	DF, RT, GR, etc.)	12. County	MITTITI	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSCOUNT REPORT OF: **CAPTORING REVIOLAL WORK** **CHANGE PLANS** **CHANG					Lea		
NOTICE OF INTENTION TO: PLUE AND ASSISTANT ADMINISTRAL WORK PLUE	777777777777777777777777777777777777777	77777777		Jarura of Notice Report of			
Convenes and accounts of the control of the control of the convenes of the control of the contro				SUBSEQU	JENT REPORT OF:		
Convenes and accounts of the control of the control of the convenes of the control of the contro		٦		[V	ALTER	ING CASING	
Change Plans Ch	PERFORM REMEDIAL WORK		PLUG ANT ABANDON		<u> </u>		
77. Cescrize 1 iccoons or Completed Operations (Clearly state all personens details, and give personens dates, including estimated date of starting any proposed by SEE HOLE 103. Moved in service unit 2-4-80. Ran a cast iron bridge plug set at 6750'. Perforated 6114'-20', 6124'-29', 6154'-59', 6209'-13'', 6284'-92', 6380'-84', 6437'-42' with 2 JSPF. Ran tubing, packer, and tailpipe. Packer set at 5646'. Tailpipe at 6021'. Acidized with 6000 gal 15% NE acid. Flushed with 40 bbl fresh water. Currently shut-in evaluating additional completion. Thereby centry that the information above is true and complete to the best of my knowledge and belief. But yours Assistant Admin. Analyst 2-25-80 Orig. Signed by Jerry Sexton	_	_					
7. Preservice 1 response or Completed Operations (Clearly state oil pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see HULE 1103. Moved in service unit 2-4-80. Ran a cast iron bridge plug set at 6750'. Perforated 6114'-20', 6124'-29', 6154'-59', 6209'-13'', 6284'-92', 6380'-84', 6437'-42' with 2 JSPF. Ran tubing, packer, and tailpipe. Packer set at 5646'. Tailpipe at 6021'. Acidized with 6000 gal 15% NE acid. Flushed with 40 bbl fresh water. Currently shut-in evaluating additional completion. Thereby cently that the information above is true and complete to the best of my knowledge and belief. Bob Casa Assistant Admin. Analyst our 2-25-80 Orig. Signed by Jerry Sexton The Packer Sexton	PULL OR ALTER CASING	ا	CHANGE PLANS				
Moved in service unit 2-4-80. Ran a cast iron bridge plug set at 6750'. Perforated 6114'-20', 6124'-29', 6154'-59', 6209'-13'', 6284'-92'', 6380'-84'', 6437'-42' with 2 JSFF. Ran tubing, packer, and tailpipe. Packer set at 5646'. Tailpipe at 6021'. Acidized with 6000 gal 15% NE acid. Flushed with 40 bbl fresh water. Currently shut-in evaluating additional completion. ***Cherchy centry that the information where it true and complete to the best of my knowledge and below. ***Book Lawrence 1093.** ***Descript Fig. 2007.** ***Cherchy centry that the information where it true and complete to the best of my knowledge and below. ***Descript Fig. 2007.** ***Desc				OTALA			
Moved in service unit 2-4-80. Ran a cast iron bridge plug set at 6750'. Perforated 6114'-20', 6124'-29', 6154'-59', 6209'-13'', 6284'-92', 6380'-84', 6437'-42' with 2 JSPF. Ran tubing, packer, and tailpipe. Packer set at 5646'. Tailpipe at 6021'. Acidized with 6000 gal 15% NE acid. Flushed with 40 bbl fresh water. Currently shut-in evaluating additional completion. Completion	· 						
Moved in service unit 2-4-80. Ran a cast iron bridge plug set at 6750'. Perforated 6114'-20', 6124'-29', 6154'-59', 6209'-13', 6284'-92'; 6380'-84', 6437'-42' with 2 JSPF. Ran tubing, packer, and tailpipe. Packer set at 5646'. Tailpipe at 6021'. Acidized with 6000 gal 15% NE acid. Flushed with 40 bbl fresh water. Currently shut-in evaluating additional completion. Completion	.7. Describe Frojosed or Co	ompleted Operations (Clea	rly state all pertinent de	tails, and give pertinent dates, incl	luding estimated date of .	starting any proposed	
Orig. Signed by Jerry Sexton Titte Deat Super	tubing, packer gal 15% NE aci	, and tailpipe.	Packer set at	5646'. Tailpipe at 6	oUZI. Acidize	d with 6000	
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Titte Dest Super							
Orig. Signed by Jerry Sexton Titte Dest Super							
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Diet I Supplement of the supplement							
Orig. Signed by Jerry Sexton Diet I Supplement of the supplement							
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Diet I Supplement of the supplement	•	•					
Orig. Signed by Jerry Sexton Diet Super							
Orig. Signed by Jerry Sexton Titte FEB 28 1981	is, I hereby certify that the	information above is true	and complete to the best	of my knowledge and belief.			
Orig. Signed by Jerry Sexton Titte FEB 28 1981		1. (1)	_			- 00	
Pret I Super	NIGHED BC	10 Laurs	117C A	ssistant Admin. Analy	st2-2	5-80	
Post I Super		Orio Signed by				La Se de Merchen	
Pret I Super					FF	Bry Hon	
0+4 NMOCD-H, 1-Hou, 1-Susp, 1-BD Expires 2/28/8/	APPROVED BY		TITLE				
0+4 NMOCD-H, 1-Hou, 1-Susp, 1-BD 67 peres a/2 8/01	CONDITIONS OF APPROV	AL, IF ANYI	501.	1/90/0	/		
	0+4 NMOCD-H, 1	-Hou, 1-Susp, 1-	-BD GXJ	ures a/k o/ o)			

OIL CONCERNATION DIV.

LEB ST .80