

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company - Div of Atlantic Richfield Company		8. Farm or Lease Name State 157 "D" #
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 11
4. Location of Well UNIT LETTER <u>I</u> <u>2123</u> FEET FROM THE <u>South</u> LINE AND <u>1644</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Arrowhead Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3461.9' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to temporarily abandon well in the following manner:

1. MIRU, POH w/rods & pump. POH w/tbg.
2. Set CIBP @ 3600'. Press test to 1000#.
3. Circ hole w/corrosion inhibited water.
4. Cap w/2" plug valve.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven D. Smith

TITLE Area Prod Supt.

DATE 8/05/87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE AUG 11 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 5 1981
OCCO
HOBBS OFFICE

RECEIVED
AUG 5 1981
OCCO
HOBBS OFFICE