

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-031670B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Burger B-20 No. 2

9. API Well No.

30-025-26540

10. Field and Pool, or Exploratory Area

Blinkey/Warren Subb Oil

11. County or Parish, State

Lea, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco Inc.

3. Address and Telephone No.

10 Dista Dr, Ste 100 W, Midland, TX (915) 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL & 1980 FEL

Unit letter G, Sect. 20, T20S, R38E

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other

Acidize

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

3-12-91 Pmp 500 gal Xylene & flush w/45 bbls H.O. Swab back to btry. Install BOP TFF at 6708 + POH w/208 jts 2 3/8" button, tbg anchor, SN & 2 3/8" OEMA. WITH w/7" cog scraper + tbg to 6700. POH w/tbg + scraper. WITH w/7" RBP, pkr + 2 3/8" tbg. Set RBP at 6700 + pkr at 6433. Pmpd 26 bbls 15% HCL-NE-FE acid, flush w/40 bbls comp fluid 5 bpm at 900 psi. Reset RBP at 6150 + tst to 1000 psi. Reset pkr at 5750. Pmpd 500 gal Xylene 1000 gal 15% HCL 4 bpm at 2500 psi. 151P - 1100 psi, 2 min - vac. SDON. Release RBP + pkr + POH w/tbg + tools. WITH w/2 3/8" OEMA at 6663, SN at 6633, tbg anchor at 5098 + total 210 jts 2 3/8" buttons tbg. Tbg anchor w/12 points + install WH. WITH w/1 1/4" pmp. RD.

AC

14. I hereby certify that the foregoing is true and correct

Signed

Christine L. Neff

Title

Admin. Assistant

Date

5-15-91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date