## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HOI MO MINTERNED DE		
we. of Corice Scrives		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR	1	1

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 . Revised 10-1-78

DISTRIE	- UTION	٠	SE NEW	MEXICO 87501		
BANTAPE		SANTA FE, NEW MEXICO 87501			Sa. Indicate Type of Lease	
FILE		-			State (X) Fee	
U.S.G.S.	<del></del>	4	5, State Oil 6 Gas Lease No.			
OPERATOR		┪ .	E-9141-1			
07442104		_			E-9141-1	
	CLAND	RY NOTICES AND RE	PORTS ON	WELLS		
(80 MET V	1000 THIS FOR THE 201	<u> VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</u>				
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	USE "APPLICA	TIDA FOR PERSON - IFORM C	-1011704 846		7. Unit Agreement Name	
٠. الله	tit.	8. Farm of Lease Hame				
week L		8, Form or Lease Hame				
2. Name of Operat		Llano "3" State Com.				
	inerals, Inc	•			9. Well No.	
J. Address of Ope	rator	1				
Р	. 0. Box 1320	10. Field and Pool, or Wildcat				
4. Location of We	11					
	н .	1980 PEET FROM THE	North	LINE AND 660 PEET PE	mmmmmm "	
UNIT LETTER						
_	ast	710H 3 TOWNS	22	34		
746E	USC LINE, SECT	/10H TOWNS				
mmm	mm	15. Elevation	Show whether	DF, RT, GR, etc.)	12. County	
15. Elevation (Show whether DF, RT, GR, etc.) 3592.5 GL					Lea ()))	
(		111111			Oal as Dage	
16.	Check	Appropriate Box To	Indicate N	lature of Notice, Report or	Other Data	
		INTENTION TO:		SUBSEQUE	ENT REPORT OF:	
	NOTICE OF			_		
	<b>—</b>	PLUE AND	ABANDON [	REMEDIAL WORK	ALTERING CASING	
	* ****  -	7500 1340		COMMENCE DRILLING OPHS.	PLUS AND ABANDONMENT	
TEMPORARILY AS	****			CASING TEST AND CEMENT JOS		
PULL OR ALTER C	A9186 L.	CHANGE P	rvas [	Recompletion		
			<u></u>	OTHER		
97 HE A						
		- Classly state a	Il pertinent des	ails, and give pertinent dates, inclu-	ding extimated date of starting any proposes	
17, Describe Pro wprk) SEE R	posed or Completed	Obetations (Creary state at	it periode a			
white and		•			D am vinclino at	
4-29-83	Run GR-PDC	log & tied in w	/existing	logs, Set 7-5/8" CIB	P ON WITELINE at	
thru						
5-17-83	721 8780	-8816' 8824'-30	'. 8837' <i>-</i>	39', 8846'-48' w/2 JSP	F 108 total	
2-17-03		30010 , 302 . 30	,	•		
	shots.					
	0 - 2 - 1 2	./10 000 gale 15%	HCI TY	eated in 4 equal stage	es separated by	
	ACIGIZEG V	Acidized w/10,000 gals 15% HCL. Treated in 4 equal stages separated by 350# rock salt and 150# Benzoic acid flakes. Flush w/2000 gals 2% KCL.				
	350# rock	salt and 150# be	MZOIC aci	u Hakes. Hush Wites	,	
	Oily gas s	show indicated.				
				150 113 . 33 -4 00 V	N wtw and	
	Frac gross interval 8750'-8848' w/1,152 bbls gelled 2% KCL wtr and					
	90.000# 20	0-40 sand.			_	
	•					
	Suah dry :	after load recove	rv. Wel	shut-in for further o	evaluation.	
	Swab dry	7, 66, 1000 . 665.6				
	·					
18. I hereby cert	tily that the informer	ton above to the and compl	ele to the beat	of my knowledge and belief.		
		/W//ann			r 04 03	
Δ1	Klaar (	UN LAU(!) \	Vi	ce President-Engineeri	ng 5-24-83	
***************************************						
A	PIGINAL SIGNED	BY JERRY SEXTON			MAY 26 1983	
<b>D</b>	DISTRICT I	SUPERVISOR			W A	

Expires 5/26/84

RECEIVED.

MAY 25 1983

HOBUS CALLES