## N. M. OIL CONS. COMMISSIE

Dec. 1973 P. O. BOX 1980		Form Approved.
UNITED STATES HOBBS, NEW MEXIC	9844Q <sub>SE</sub>	Budget Bureau No. 42-R1424
DEPARTMENT OF THE INTERIOR	l .	063458
GEOLOGICAL SURVEY	6. IF INDIAN, AL	LOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREE	MENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	NMA	=1/_
1 oil	O FARM OR LEA	
well gas well other	9. WELL NO.	n Unit
2. NAME OF OPERATOR CONOCO INC.	8:	
3. ADDRESS OF OPERATOR	10 FIELD OR WIL	DCAT NAME / P
P. O. Box 460, Hobbs, N.M. 88240	1 - 1 - 1 / H	, OR BLK. AND SURVEY OR
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> </ol>	AREA	
AT SURFACE: 1980 FNL & 1980 FEL	Sec. 35	,T-205,R-38E
AT TOP PROD. INTERVAL:	12. COUNTY OR F	PARISH 13. STATE
	14. API NO.	NM
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS	(SHOW DF, KDB, AND WD)
EST WATER SHUT-OFF  RACTURE TREAT  HOOT OR ACIDIZE  EPAIR WELL  ULL OR ALTER CASING  ULTIPLE COMPLETE  HANGE ZONES  BANDON*  When Downhole Commingle	change on F	·
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dirmeasured and true vertical depths for all markers and zones pertinent 9/8/ POOH w/rods and tubing. Mill over sted on 4/27/8/: 60 BO, 131 BW, 5 No mations! Blineby Tubb	to this work.)* - pkv. POOH.	re subsurface locations and
occ alm. ord. OHC 337	NIEGIE I	20025111
• •		0.1001
	US OCT 1	6 1981 🔠
	OIL 8 U.S. GEOLOC ROSWELL, N	CAS FICAL SURVEY EV/ MEXICO
ubsurface Safety Valve: Manu. and Type		Sat @
8. I hereby certify that the foregoing is true and correct		. vec @ Ft.
GNED W/4 Q. Butter fred TITLE Advain Supervi	SOL DATE DOT	ber 14.1981
ACCEPTED FOR RECORDS Space for Federal or State office	us <b>e)</b>	
NDITIONS OF APPROVAL, IF ANY:	DATE	
00T 2 0 <b>1981</b>		

U.S. GIOLOGICAL SURVEY
ROSWILL, NUV MEXICOSee Instructions on Reverse Side