

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-025-26976

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

L-4780

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER

Name of Operator
Pogo Producing Company

Lease Name or Unit Agreement Name

NBR

Address of Operator
P. O. Box 10340, Midland, TX 79702-7340

Well No.

1

Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 18 Township 22 Range 33 NMPM Lea County

Elevation (Show whether DF, RKB, RT, GR, etc.)

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ~~Extend TA status~~ ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pogo Producing Company was recently denied permission to extend the SI status of the above captioned well. As per conversation with Gary Wink Pogo plans to either TA, P&A or return the NBR #1 to production. One of these options will be performed within 90 days.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Cathy Tomberlin

TITLE Operation Tech

DATE 07-14-00

TYPE OR PRINT NAME Cathy Tomberlin

TELEPHONE NO. 915-685-8100

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:



Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 3088
Santa Fe, New Mexico 87504-3088

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 88, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL APPLICANT

30-105-25375

5. Indicate Type of Lease

STATE ☒

FED ☐

6. State Oil & Gas Lease No.

1-1780

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

POGO PRODUCING COMPANY

3. Address of Operator

P. O. BOX 10340, MIDLAND, TEXAS 79702

7. Lease Name or Unit Agreement Name

NBR ~~6456~~

8. Well No.

1

9. Pool name or Wildcat

Booted Ridge

4. Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line
Section 18 Township 22-S Range 33-E NMPM Lea County

10. Elevation (Show whether SP, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☒

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Richard A. Wright

TITLE Division Operations Manager

TELEPHONE NO.

TYPE OR PRINT NAME

This space for State Use

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY

TITLE

DATE

MAR 06 1997

105 10 104

53728

Received
Hoots
OOD

53789

53789

POGO NBR STATE WELL NO. 1
1980' FSL and 1980' FEL
Section 18, T-22-S, R-33-E
Lea County, New Mexico

Page 1

P: AtkBk 13756-765'
P: Atk 13865-895'
P: Mrw 14739-763'

Re-establish Atoka Bank Production

TD 15120' CIBP 13910' CIBP 13845'

11/25/96 MIRU WSU, prep to release packer.
11/26/96 Rls pressure, POOH, found 2 jt w/ hole; XO BOP gasket.
TIH w/ pkr, drop SV, tbg failed to test, POOH. SDFN.
11/27/96 Test tbg to 8500 PSI, set pkr @ 13445'.
11/28-29/96 SD for Thanksgiving.
11/30/96 Move pkr to 13069'. Cmt sqz Atoka perfs.
12/01/96 POOH pkr, tag cmt @ 13068', drl to 13130'.
12/02/96 Drl cmt.
12/03/96 Drld cmt & junk 13849-13860'
12/04/96 Trip for new bit, make up shoe & TIH.
12/05/96 Mill on CIBP @ 13860', stuck @ 13888', worked free,
continue to work BP dn hole but shoe was dragging in csg,
POOH.
12/06/96 Bleed csg & tbg & finish POOH. SI well for day to build
fishing tool.
12/07/96 TIH to 13888', mill on BP & push dn hole (short 13').
12/08/96 Push BP to 13911', ran GR 13915-13370'.
12/09/96 Drl junk @ 13890-13891.
12/10/96 Mill 13891-13899', circ hole clean, TOOH tbg & mill.
12/11/96 Test tbg.
12/12/96 Set pkr @ 13791', disp hole w/ brine. Swab.
12/13/96 Swab.
12/14-15/96 SDFWE, prep to swab.
12/16/96 Swab.
12/17/96 POOH tbg.
12/18/96 TP Ø. POOH pkr & sent for repair (?nothing wrong).
12/19/96 Test tbg to 10000 PSI, hold 1 min.
12/20/96 Test tbg to 10000 PSI, hold 1 min. Set pkr @ 13788'.
12/21/96 Circ pkr fluid, test pkr to 500 PSI 30 min (OK). Swab.
12/22/96 Swab, possible paraffin plug @ 10500'.
12/23/96 Swb to obstruction @ 10000', pmp condensate dn tbg,
communication established w/ annls when pressure reached
4300 PSI, apparent tbg leaking @ 13744-13765'. Made 1
more swb run, plg still in tbg @ 10000'.
12/24/96 SD, WOO.
12/25/96 SD for Christmas, WOO.
12/26/96 RDMO service unit, WOO.
12/28/96 -
2/28/97 SI, WOO.