

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-27261
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name William Turner
8. Well No. 4
9. Pool name or Wildcat Blinebry Oil & Gas (oil)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3488' KB 3474'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 29 Township 21-S Range 37-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3488' KB 3474'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **RC in Blinebry** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/26/98 MIRU PU. POOH w/rods & pump. ND wellhead. NU BOP. POOH w/2 3/8" tbg. RIH w/pkr, set at 5780'.
Test, OK. POOH. RIH w/RBP, set at 5780'.
3/29/98 Perforate Blinebry 5726-62' w/4 SPF, 90 deg phasing.
3/30/98 RIH w/pkr, set at 5765'. Test RBP. Rel pkr & pickle tbg w/600 gals 15% acid. Reset pkr at 5652'.
Acidize 5726-62' w/2000 gals 15% acid. Swab well.
3/31/98 Frac w/39,000 gals 25# crosslinked gel w/124,000 lbs of 16/30 white sand. Swab well. Flow well
to test tank.
4/4/98 Rel pkr, POOH. RIH w/RBP overshot, rel RBP, POOH. RIH w/5" RBP, set at 6700'. Spot w/1 sx sand.
4/5/98 RIH w/2 3/8" prod tbg at 5799'. ND BOP. NU BOP. TAC at 5574'. RIH w/pump & rods. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 4/9/98
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TITLE STATE DATE 'APR 28 1998
CONDITIONS OF APPROVAL, IF ANY: Stacy ZA Wentz Abc dp