

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
1980

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-031695A B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

Warren Unit

2. NAME OF OPERATOR

Conoco Inc.

8. FARM OR LEASE NAME

Warren Unit Bl. Bty 1

3. ADDRESS OF OPERATOR

P.O. Box 460, Hobbs, NM 88240

9. WELL NO.

91

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit F

10. FIELD AND POOL, OR WILDCAT

Blindey Oil & Gas

11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA

Sec. 33-205-38E

14. PERMIT NO.

30-025-27566

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3513' RF

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Acidize Open Add pay

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

(Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MDRU. Unseat pmp. PootH w/pmp. TOF at 6239'. WITH w/csg scraper to 6200'. Spot 220 gal 15% HCl acid from 6020'-5800'. Perf w/1 sspt at 5868'-6004'. Set RBP at 6023' & test to 2000 psi. Set plv @ 5929'. Acidize Blindey zone w/2000 gals 15% HCl acid. Pumped 12 bbls flush. Pull plv above all perms & set at 5774', pumped 13 bbl flush. Swab. WITH w/plv & set at 5743'. Acidize Blindey w/33 bbl 15% HCl acid w/5% Checkersol. Flush w/30 bbl TFW. Swab.

2. Finish out hole w/RBP & plv. WITH w/production equipment. Rig down.

Work started 12-31-86 Spool: 4130, 52BW, 3 mcf
Work Completed 1-9-87

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature] J. F. FINNEY

TITLE

Administrative Supervisor

DATE

March 6, 1987

(This space for Federal or State office use)

APPROVED BY

TITLE

ACCEPTED FOR RECORD

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 15 1987

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) ARCO(2) AMOCO(2) Chevron(1) File

RECEIVED
MAR 19 1987
OCD
HOBBS OFFICE