

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27704
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  Raley "A"
8. Well No. 1
9. Pool name or Wildcat W. Nadine Blinebry
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3582' RKB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Tamarack Petroleum Company, Inc.	3. Address of Operator 500 W. Texas, Suite 1485, Midland, TX 79701	4. Well Location Unit Letter <u>P</u> : <u>990</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>20S</u> Range <u>38E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3582' RKB			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Open Additional Blinebry pay</u> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU PU. POOH w/rods, pump and tubing.
2. Run bit and scraper to 6450'. Spot acid.
3. Perforate 5821-5905' (16 holes), 5924-5940' (7 holes), 6080-6128' (12 holes), 6188-6243' (10 holes), 6292-6395' (16 holes).
4. Isolate each zone with packer & bridge plug, acidize with total of 13,950 gals. 15% NEFE acid.
5. Swab back load.
6. Return well to production.

Estimated starting date: 7/25/96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Hal Gill TITLE District Engineer DATE 7/10/96

TYPE OR PRINT NAME Hal Gill TELEPHONE NO. 915/683-5474

(This space for State Use)

JUL 12 1996

APPROVED BY DAVID LARRY SEXTON TITLE Assistant District Engineer DATE 7/10/96

CONDITIONS OF APPROVAL, IF ANY: