

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name ---
2. Name of Operator MORRIS R. ANTWEIL	8. Farm or Lease Name HERMAN
3. Address of Operator P. O. Box 2010, Hobbs, New Mexico 88240	9. Well No. 4
4. Location of Well UNIT LETTER <u>L</u> , 1980 FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3566' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Perforate, treat & test</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pumped 12 BO, 4.9 BW and 27.6 MCF per day. Pulled rods, pump & tbg. Perforated Blinbry with single shots at 5988', 5989½, 5993½, 5994½, 6015½ & 6016½' (6 holes). Set Retrievable bridge plug at 6200' and packer at 5930'. Acidized perms with 2000 gals 15% NEFE acid at 4.7 BPM & 3950 psi. Max press 4200; ISIP 3100; 15 min SIP 2800. Flowed & swabbed back load. Swabbed .65 BO & .35 BW per hour. Preparing to fracture treat.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 11/11/82

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE NOV 15 1982

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 12 1962

A.C.D.
HOBBS OFFICE