

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR. (CATE)
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-55963

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Harris Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

W. Grama Ridge Bone Spring

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SJS

SS, T22S, R34E

12. COUNTY OR PARISH

13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

C. W. Trainer

3. ADDRESS OF OPERATOR

c/o Oil Reports & Gas Service, Inc. P.O.Box 755, Hobbs, NM 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL & 1980' FEL of Sec. 5

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3611 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANT

(Other) Perf & Test Delaware

X

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work began 10/16/89. Set RBP at 6946, perf 6001-6011 with
4 shots per foot, swab 100% water. Set EZ Drill plug at 5995
& cap with 15 sacks cement. Tag top of plug at 5940. Perforate
5790 to 5810, swab 100% water. Well temporarily abandoned
10/25/89.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Halls

TITLE

Agent

DATE

10/26/89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SJS

RECEIVED

OCT 30 9 20 AM '89